Problem Wk.4.1.2: Step Signal

Read the handout for the software lab.

Write a new subclass of Signal called stepSignal that has value 0 at any time n < 0 and value 1 otherwise.

class StepSignal(Signal):

MIT OpenCourseWare http://ocw.mit.edu

6.01SC Introduction to Electrical Engineering and Computer Science Spring 2011

For information about citing these materials or our Terms of Use, visit: http://ocw.mit.edu/terms.